

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

ST. PATRICK'S CATHOLIC CHURCH
619 Tenth Street, NW
Washington
District of Columbia

HABS DC-863

INDEX TO BLACK AND WHITE PHOTOGRAPHS

Jack E. Boucher, photographer

DC-863-1	Interior view, aisle
DC-863-2	Interior view looking down aisle to chancel
DC-863-3	Interior view looking down aisle to chancel and altar
DC-863-4	Interior view, vaulting and stained glass in aspe
DC-863-5	Interior view, side aisle
DC-863-6	Interior view, pulpit and chapel at end of side aisle
DC-863-7	Closer view of pulpit and chapel
DC-863-8	Interior view, chapel
DC-863-9	Interior view, pulpit and cross aisle
DC-863-10	Interior view, pulpit with scale
DC-863-11	Detail view of the pulpit, with scale
DC-863-12	Perspective view of pulpit
DC-863-13	Interior view, altar rail and side altar
DC-863-14	Interior view looking to side altar
DC-863-15	Interior view looking to side altar

ST. PATRICK'S CATHOLIC CHURCH

HABS DC-863

INDEX TO PHOTOGRAPHS

(Page 2)

DC-863-16	Interior view, close view of the side altar
DC-863-17	Interior view, looking toward narthex; note rose window
DC-863-18	Interior view, looking from the altar down side aisle
DC-863-19	Interior view, detail of altar rail
DC-863-20	Interior view, detail of column capital
DC-863-21	Interior view, detail showing the baptismal font
DC-863-22	Interior view, detail of pilaster capital with scale
DC-863-23	Interior view, side altar